

Test Report

Number: TWNT01715262

Applicant: Excelassoc Co., Ltd.

10/F., No. 152, Cheng De Rd., Sec. 4,

71101 04 2010

Taipei,

Taiwan, R.O.C.

Date: Jun 12, 2019

Date Received:	JUN 04, 2019
Order No.:	-
Description:	Woven fahric Dye & Moisture Management Finished 4-way stretch

Order No.:	-
Description:	Woven fabric, Dye & Moisture Management Finished, 4-way stretch
Colour(s):	White
Supplier:	Excelasso Co., Ltd.
End Use:	-
Quoted Composition:	100% Polyester
Ref/Style/Stroke No.:	ART. 12800
Buying Division:	-
Agent Name:	-
Quality:	-
Batch No.:	-
Spec. No.:	-
Department:	-
Stroke/Design Ref.:	-
Phy Perf Code:	-
Colour Perf Code	-
Inductative Care Ref Code:	-
Additional Details:	-

Authorized By:

On behalf of Intertek Testing Services

Taiwan Limited

Carol Peng

General Manager

Page 1 of 2

sally/bella

Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2400 · 6602-2401



-Residual Extension

Test Report

Number: TWNT01715262

Tests Conducted (As Requested By The Applicant)

1 Extension, Residual Extension Of Stretch Woven Fabric:

Provided Requirement

Average Warp Average Weft
-Extension At 4.5 kg Load 12.9% 23.9%
-Modulus At 40% -# -#
Extension

1.1%

4.0% Max 5.0%

Remark: The test method was requested by applicant.

The load cannot be measured due to the extension at specified load 4.5 kg was less than 40%.

End of Report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: http://www.intertek-twn.com/terms/. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.



Page 2 of 2



11492 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2400 · 6602-2401

